

Colorado Department of Labor and Employment Division of Oil and Public Safety – Compliance Section 633 17<sup>th</sup> Street, Suite 500 Denver, CO 80202-3610 Phone: 303-318-8547

Email: cdle\_oil\_inspection@state.co.us

Web: www.colorado.gov/ops

## Approved Products for the Repair of Spill Buckets and Piping Containment Sumps

The following products have received OPS approval for use in the repair of spill buckets and piping containment sumps used for interstitial monitoring. All manufacturer recommendations, requirements and installation instructions must be strictly followed, including installer training where provided.

All equipment must be tightness tested with passing results before being returned to service. Repairs and tightness testing can only be performed by an OPS Qualified Service Technician (QST). All repairs and testing must be documented on the <u>Minor Equipment Repair/Replacement Notification</u> and <u>Secondary Containment and Spill Prevention Equipment Tightness Testing</u> forms, and submitted to OPS within 7 days.

|                            |  |                   | Approved Use and<br>Testing Frequency After Repair |               |                  |               |
|----------------------------|--|-------------------|--|---------------|------------------|---------------|
| Manufacturer               | Product  | Sump<br>Materials | Spill Bucket                                       |               | Containment Sump |               |
|                            |  |                   | <u>1 Year</u>                                      | <u>3 Year</u> | <u>1 Year</u>    | <u>3 Year</u> |
| Emco Wheaton               | Stainless Steel Insert A1005-505   | N/A - Insert      | ×  | <b>✓</b>      | ×                | ×             |
| Icon Containment Solutions | PolyFuse<br>(standalone minor repairs)   | Poly              | <b>✓</b>   | ×             | <b>✓</b>         | ×             |
| Icon Containment Solutions | iBond Structural Bonder<br>(standalone minor repairs)                            | FRP/Steel         | <b>✓</b>   | ×             | <b>✓</b>         | ×             |
| Icon Containment Solutions | FastFix Instant Patch Repair (standalone minor repairs)                          | Poly/FRP          | ×  | ×             | <b>√</b>         | ×             |
| Icon Containment Solutions | "Blueline" Split Repair Kits<br>IRF Series BL-S thru BL-M                        | Poly/FRP          | ×  | ×             | ×                | <b>✓</b>      |
| Icon Containment Solutions | Split Repair Encapsulation Kits<br>IRF (M-XXL) Series                            | Poly/FRP          | ×  | ×             | ×                | <b>✓</b>      |
| Icon Containment Solutions | Split Repair Kits (Std/OPW/NUPI)<br>IRF B Series                                 | Poly/FRP          | ×  | ×             | ×                | <b>✓</b>      |
| Icon Containment Solutions | Split Repair Test Reducer and<br>Insert Fittings<br>ISR / IRI / INR / INI Series | Poly/FRP          | ×  | ×             | ×                | <b>✓</b>      |
| Icon Containment Solutions | Split Repair Housing Kits<br>OPW / TCI / FL / OTC Series                         | Poly/FRP          | ×  | ×             | ×                | <b>✓</b>      |
| Icon Containment Solutions | Split Repair Rigid Bonded<br>IRF Rigid Series                                    | FRP               | ×  | ×             | ×                | <b>✓</b>      |